



NATIONAL MARITIME SAFETY AUTHORITY
Navigation & Safety Services Division
Hydrographic Services Department

November 27th 2009

Notices to Mariners

Number 09 – 68

Rabaul – East New Britain Province

.....
Rabaul Rear: Fl 5s, W, 38m, 10M; Admiralty List of lights number 3498.1

Latitude: 04° 11.700' S Longitude: 152° 10.100' E

The light is restored to normal.

Please cancel Notice to Mariners number 09 – 66 for Rabaul Rear light.

Charts temporarily affected: AUS545, AUS554 and AUS680
.....

Mackenzie Shoal: Fl 10s, W, 8m, 9M; Admiralty List of lights number 3500

Latitude: 04° 15.411' S Longitude: 152° 13.445' E

The light is restored to normal.

Please cancel Notice to Mariners number 09 – 66 for Mackenzie Shoal light.

Charts temporarily affected: AUS545 and AUS680
.....

National Maritime Safety Authority

Joseph Kunda
Manager Hydrographic Services